


American
C24

Confidential
garvinm@stlouis-mo.gov
2020-01-15 17:02:15 +0000

Confidential
garvinm@stlouis-mo.gov
2020-01-15 17:02:15 +0000



EAM

Equipment History

Work Orders Completed Between 07/01/2017 and 07/31/2018

Version	11.4
Date	10/03/2018 07:12
User	128550
Equipment	05076TB292925 [PASSENGER BOARDING BRIDGE C24 - US # JW729]
Show MEC Details	No
Show Costs	No

Work Order Equipment	Completed	Problem Code	Failure Code	Cause Code	Action Code	Description
11816459	07/10/2018					CALLED TO RAMP BECAUSE BRIDGE WILL NOT MOVE
05076TB292925 (AA-STL-FAC) 11630663	PASSENGER BOARDING BRIDGE C24 - US # JW729 04/17/2018					MONTHLY PM - THYSSEN PASSENGER BOARDING BRIDGE REV F
05076TB292925 (AA-STL-FAC) 11566894	PASSENGER BOARDING BRIDGE C24 - US # JW729 05/11/2018					QUARTERLY PM - THYSSEN PASSENGER BOARDING BRIDGE REV F (Used to be AA11124)
05076TB292925 (AA-STL-FAC) 11175551	PASSENGER BOARDING BRIDGE C24 - US # JW729 07/25/2017					LIGHT ASSEMBLY OVER CONTROL CONSOL FALLING APART
05076TB292925 (AA-STL-FAC) 11145906	PASSENGER BOARDING BRIDGE C24 - US # JW729 07/18/2017					MONTHLY PM - THYSSEN PASSENGER BOARDING BRIDGE REV F
05076TB292925 (AA-STL-FAC) 11823885	PASSENGER BOARDING BRIDGE C24 - US # JW729 07/25/2018					CALLEDIN AFTER HOURS BECAUSE BRIDGE WOULDN'T MOVE
05076TB292925 (AA-STL-FAC) 11817492	PASSENGER BOARDING BRIDGE C24 - US # JW729 07/12/2018					CUSTOMER REQUESTED THAT CANOPY AND OPERATING MECHANISM BE INSPECTED
05076TB292925 (AA-STL-FAC) 11529855	PASSENGER BOARDING BRIDGE C24 - US # JW729 02/09/2018					MONTHLY PM - THYSSEN PASSENGER BOARDING BRIDGE REV F
05076TB292925 (AA-STL-FAC) 11744387	PASSENGER BOARDING BRIDGE C24 - US # JW729 06/25/2018					MONTHLY PM - THYSSEN PASSENGER BOARDING BRIDGE REV F
05076TB292925 (AA-STL-FAC) 11687617	PASSENGER BOARDING BRIDGE C24 - US # JW729 05/22/2018					MONTHLY PM - THYSSEN PASSENGER BOARDING BRIDGE REV F
05076TB292925 (AA-STL-FAC) 11583452	PASSENGER BOARDING BRIDGE C24 - US # JW729 03/02/2018					PM WRITE UPS
05076TB292925 (AA-STL-FAC) 11310211	PASSENGER BOARDING BRIDGE C24 - US # JW729 10/19/2017					MONTHLY PM - THYSSEN PASSENGER BOARDING BRIDGE REV F
05076TB292925 (AA-STL-FAC) 11336820	PASSENGER BOARDING BRIDGE C24 - US # JW729 10/19/2017					CUSTOMER REQUESTED BRIDGE BE CHECKED OUT WHEN CONTRACTOR IS DONE
05076TB292925 (AA-STL-FAC) 11170755	PASSENGER BOARDING BRIDGE C24 - US # JW729 07/18/2017					PM WRITE UPS
05076TB292925 (AA-STL-FAC) 11769019	PASSENGER BOARDING BRIDGE C24 - US # JW729 06/21/2018					PM WRITE UPS

Work Order Equipment	Completed	Problem Code	Failure Code	Cause Code	Action Code	Description
05076TB292925 (AA-STL-FAC) 11540385		PASSENGER BOARDING BRIDGE C24 - US # JW729				NO FUNCTIONS, BRIDGE WILL NOT MOVE
05076TB292925 (AA-STL-FAC) 11338571		PASSENGER BOARDING BRIDGE C24 - US # JW729				CALLED IN ON sATURDAY FOR COMBINATION LOCK ON RSMP DOOR INOP
05076TB292925 (AA-STL-FAC) 11242908		PASSENGER BOARDING BRIDGE C24 - US # JW729				LOOSE HANDRAILS, BOLTS ON SERVICE STAIRS LOOSE, SEVERAL FLOURESCENT BULBS OUT.
05076TB292925 (AA-STL-FAC) 11062037		PASSENGER BOARDING BRIDGE C24 - US # JW729				QUARTERLY PM - THYSSEN PASSENGER BOARDING BRIDGE REV F (Used to be AA11124)
05076TB292925 (AA-STL-FAC) 11770855		PASSENGER BOARDING BRIDGE C24 - US # JW729				RAMP CALLED AND DOUBLE DOORS WILL NOT STAY OPEN
05076TB292925 (AA-STL-FAC) 11419124		PASSENGER BOARDING BRIDGE C24 - US # JW729				PM WRITE UPS
05076TB292925 (AA-STL-FAC) 11853777		PASSENGER BOARDING BRIDGE C24 - US # JW729				PM WRITE UPS
05076TB292925 (AA-STL-FAC) 11822717		PASSENGER BOARDING BRIDGE C24 - US # JW729				LATGE DENT IN ONE OF THE DECK PANELS AT TOP OF SERVICE STAIRS
05076TB292925 (AA-STL-FAC) 11572917		PASSENGER BOARDING BRIDGE C24 - US # JW729				MONTHLY PM - THYSSEN PASSENGER BOARDING BRIDGE REV F
05076TB292925 (AA-STL-FAC) 11197952		PASSENGER BOARDING BRIDGE C24 - US # JW729				MONTHLY PM - THYSSEN PASSENGER BOARDING BRIDGE REV F
05076TB292925 (AA-STL-FAC) 11797916		PASSENGER BOARDING BRIDGE C24 - US # JW729				MONTHLY PM - THYSSEN PASSENGER BOARDING BRIDGE REV F
05076TB292925 (AA-STL-FAC) 11288480		PASSENGER BOARDING BRIDGE C24 - US # JW729				PM WRITE UPS, HARDWARE LOOSE ON STAIRS AND LIGHTS OUT IN TUNNEL
05076TB292925 (AA-STL-FAC) 11257496		PASSENGER BOARDING BRIDGE C24 - US # JW729				MONTHLY PM - THYSSEN PASSENGER BOARDING BRIDGE REV F
05076TB292925 (AA-STL-FAC) 10800266		PASSENGER BOARDING BRIDGE C24 - US # JW729				ANNUAL PM - THYSSEN PASSENGER BOARDING BRIDGE REV F (Used to be AA11125)

Work Order Equipment	Completed	Problem Code	Failure Code	Cause Code	Action Code	Description
05076TB292925 (AA-STL-FAC) 11662086	04/23/2018	PASSENGER BOARDING BRIDGE C24 - US # JW729				PM WRITE UPS.
05076TB292925 (AA-STL-FAC) 11601230	03/09/2018	PASSENGER BOARDING BRIDGE C24 - US # JW729				PM WRITE UPS
05076TB292925 (AA-STL-FAC) 11472109	01/28/2018	PASSENGER BOARDING BRIDGE C24 - US # JW729				MONTHLY PM - THYSSEN PASSENGER BOARDING BRIDGE REV F
05076TB292925 (AA-STL-FAC) 11389499	11/16/2017	PASSENGER BOARDING BRIDGE C24 - US # JW729				REPLACEMENT OF LIFT TOWER WEAR PADS AND CANOPY STRAPS
05076TB292925 (AA-STL-FAC) 11364402	11/08/2017	PASSENGER BOARDING BRIDGE C24 - US # JW729				MONTHLY PM - THYSSEN PASSENGER BOARDING BRIDGE REV F
05076TB292925 (AA-STL-FAC) 11445865	12/21/2017	PASSENGER BOARDING BRIDGE C24 - US # JW729				TUNNEL ROLLER REPLACEMENT PROJECT
05076TB292925 (AA-STL-FAC) 11429665	12/14/2017	PASSENGER BOARDING BRIDGE C24 - US # JW729				MONTHLY PM - THYSSEN PASSENGER BOARDING BRIDGE REV F
05076TB292925 (AA-STL-FAC) 11227421	02/27/2018	PASSENGER BOARDING BRIDGE C24 - US # JW729				QUARTERLY PM - THYSSEN PASSENGER BOARDING BRIDGE REV F (Used to be AA11124)
05076TB292925 (AA-STL-FAC)		PASSENGER BOARDING BRIDGE C24 - US # JW729				