

Runway 30L Existing Obstruction Table																										
		Part 77 Approach				Departure Surface				Threshold Stop Surface				VGS Surface				PAPI				TIRPS Visual Surface				
Object ID	Description	Object Elevation (MSL)	Surface Elevation (MSL)	Penetration/ Clearance (ft)	Surface Elevation (MSL)	Penetration/ Clearance (ft)	Surface Elevation (MSL)	Penetration/ Clearance (ft)	Surface Elevation (MSL)	Penetration/ Clearance (ft)	Surface Elevation (MSL)	Penetration/ Clearance (ft)	Surface Elevation (MSL)	Penetration/ Clearance (ft)	Surface Elevation (MSL)	Penetration/ Clearance (ft)	Surface Elevation (MSL)	Penetration/ Clearance (ft)	Surface Elevation (MSL)	Penetration/ Clearance (ft)	Surface Elevation (MSL)	Penetration/ Clearance (ft)	Disposition			
2544	Fence	618.1	637.0	-18.9	655.0	-36.9	664.2	-46.1	-	-	700.3	-82.2	-	-	-	-	-	-	-	-	-	-	-	No Action		
2546	Bush	628.7	639.4	-10.7	658.0	-29.3	667.8	-39.1	-	-	704.1	-75.4	667.8	-39.1	-	-	-	-	-	-	-	-	-	No Action		
2556	Tree	632.4	639.7	-27.0	658.4	-4.4	668.2	-5.3	-	-	709.7	-72.7	668.2	-5.3	-	-	-	-	-	-	-	-	-	Airspace Study/Removal		
2557	Tree	637.0	639.9	-2.9	658.6	-21.6	668.5	-31.5	-	-	705.0	-68.0	668.5	-31.5	-	-	-	-	-	-	-	-	-	No Action		
2558	Tree	637.0	640.1	-3.1	658.9	-21.8	668.8	-31.8	-	-	705.3	-68.3	-	-	-	-	-	-	-	-	-	-	-	No Action		
2559	Bush	635.7	640.1	-4.4	659.3	-24.3	668.8	-33.1	-	-	705.6	-69.6	668.8	-33.1	-	-	-	-	-	-	-	-	-	No Action		
2560	Tree	666.3	640.1	26.2	658.9	7.4	668.8	-2.5	-	-	705.3	-39.0	668.8	-2.5	-	-	-	-	-	-	-	-	-	Airspace Study/Removal		
2561	Tree	674.9	640.2	34.7	659.9	15.9	668.9	6.0	-	-	705.4	-30.5	668.9	6.0	-	-	-	-	-	-	-	-	-	Airspace Study/Removal		
2562	Tree	636.0	640.3	-4.3	659.1	-23.1	668.1	-31.1	-	-	705.6	-49.6	668.1	-31.1	-	-	-	-	-	-	-	-	-	No Action		
2563	Bush	635.3	640.4	-5.1	659.2	-25.8	669.2	-35.8	-	-	705.7	-72.3	669.2	-35.8	-	-	-	-	-	-	-	-	-	No Action		
2564	Tree	635.1	640.4	-5.3	659.3	-24.2	669.3	-34.2	-	-	705.8	-70.7	-	-	-	-	-	-	-	-	-	-	-	No Action		
2565	Tree	645.7	640.5	25.1	659.5	16.1	669.5	-3.4	-	-	706.1	-26.6	669.5	-3.4	-	-	-	-	-	-	-	-	-	Airspace Study/Removal		
2567	Tree	627.6	640.7	-13.1	659.6	-32.0	669.2	-42.1	-	-	706.2	-78.6	669.2	-42.1	-	-	-	-	-	-	-	-	-	No Action		
2568	Tree	653.5	640.7	12.8	659.6	-6.1	669.7	-16.2	-	-	706.2	-52.7	669.7	-16.2	-	-	-	-	-	-	-	-	-	Airspace Study/Removal		
2570	Bush	634.9	640.9	-4.0	659.8	-24.9	669.5	-34.1	-	-	706.5	-71.6	669.5	-34.1	-	-	-	-	-	-	-	-	-	No Action		
2571	Bush	633.4	640.9	-7.5	659.8	-26.4	669.9	-36.5	-	-	706.5	-73.1	669.9	-36.5	-	-	-	-	-	-	-	-	-	No Action		
2572	Tree	640.3	641.1	1.2	660.1	0.3	670.3	-9.9	-	-	706.8	-45.5	670.3	-9.9	-	-	-	-	-	-	-	-	-	Airspace Study/Removal		
2573	Tree	646.1	641.2	24.9	660.2	11.3	670.3	-8.3	-	-	706.8	-40.9	670.3	-8.3	-	-	-	-	-	-	-	-	-	Airspace Study/Removal		
2575	Tree	631.4	641.3	-9.9	660.4	-29.0	670.6	-39.2	-	-	707.2	-75.8	670.6	-39.2	-	-	-	-	-	-	-	-	-	No Action		
2578	Tree	666.5	641.6	24.9	660.7	5.8	670.9	-4.4	-	-	707.8	-41.1	670.9	-4.4	-	-	-	-	-	-	-	-	-	Airspace Study/Removal		
2579	Tree	635.9	641.6	-5.6	660.7	-24.8	670.9	-35.0	-	-	707.8	-71.7	670.9	-35.0	-	-	-	-	-	-	-	-	-	No Action		
2582	Tree	668.7	641.9	26.8	661.1	7.6	671.4	-2.7	-	-	708.1	-39.4	671.4	-2.7	-	-	-	-	-	-	-	-	-	Airspace Study/Removal		
2585	Tree	628.9	642.0	-13.1	661.2	-32.3	671.6	-42.6	-	-	708.3	-79.4	671.6	-42.6	-	-	-	-	-	-	-	-	-	No Action		
2587	Tree	637.5	642.1	-4.6	661.3	-23.8	671.7	-38.2	-	-	708.4	-70.9	671.7	-38.2	-	-	-	-	-	-	-	-	-	No Action		
2588	Tree	639.1	642.1	-3.0	661.4	-23.3	671.8	-32.7	-	-	708.5	-69.4	-	-	-	-	-	-	-	-	-	-	-	No Action		
2589	Tree	666.7	642.2	24.5	661.5	5.2	671.9	-5.2	-	-	708.6	-41.9	671.9	-5.2	-	-	-	-	-	-	-	-	-	Airspace Study/Removal		
2591	Tree	634.3	642.4	-8.1	661.6	-31.4	672.1	-40.9	-	-	709.3	-75.2	672.1	-40.9	-	-	-	-	-	-	-	-	-	No Action		
2593	Bush	633.2	642.7	-9.5	662.0	-27.6	672.6	-39.4	-	-	709.3	-76.2	672.6	-39.4	-	-	-	-	-	-	-	-	-	No Action		
2595	Tree	631.0	642.8	-11.8	662.7	-31.2	672.8	-41.7	-	-	709.6	-78.6	672.8	-41.7	-	-	-	-	-	-	-	-	-	No Action		
2598	Tree	640.0	642.8	-18.1	662.2	-1.3	672.8	-11.8	-	-	709.6	-68.0	672.8	-11.8	-	-	-	-	-	-	-	-	-	Airspace Study/Removal		
2599	Tree	631.4	643.2	-11.8	662.7	-31.3	673.3	-41.9	-	-	710.2	-78.8	673.3	-41.9	-	-	-	-	-	-	-	-	-	No Action		
2600	Tree	647.4	643.2	4.2	662.8	-15.6	673.4	-38.2	-	-	710.2	-60.2	673.4	-38.2	-	-	-	-	-	-	-	-	-	Airspace Study/Removal		
2601	Bush	643.1	643.2	-0.1	662.8	-15.6	673.4	-39.2	-	-	710.3	-76.1	673.4	-39.2	-	-	-	-	-	-	-	-	-	No Action		
2602	Tree	659.8	643.3	16.6	662.8	-3.0	673.4	-13.6	-	-	710.3	-50.5	673.4	-13.6	-	-	-	-	-	-	-	-	-	Airspace Study/Removal		
2604	Tree	671.8	643.5	28.3	663.1	10.1	673.8	-1.0	-	-	710.7	-61.8	673.8	-1.0	-	-	-	-	-	-	-	-	-	No Action		
2605	Tree	664.6	643.6	21.0	663.2	1.4	673.9	-6.3	-	-	710.8	-46.2	673.9	-6.3	-	-	-	-	-	-	-	-	-	Airspace Study/Removal		
2606	Tree	639.1	644.0	-4.8	663.7	-24.6	674.5	-35.4	-	-	711.5	-72.3	-	-	-	-	-	-	-	-	-	-	-	No Action		
2607	Tree	638.7	644.0	-5.3	663.7	-24.6	674.5	-35.4	-	-	711.6	-71.0	674.5	-35.4	-	-	-	-	-	-	-	-	-	Airspace Study/Removal		
2609	Tree	685.1	644.2	40.9	663.9	21.2	674.8	10.3	-	-	711.7	-26.6	674.8	10.3	-	-	-	-	-	-	-	-	-	Airspace Study/Removal		
2610	Bush	639.7	644.2	-4.5	664.0	-24.3	674.8	-35.2	-	-	711.8	-72.1	674.8	-35.2	-	-	-	-	-	-	-	-	-	No Action		
2611	Tree	640.5	644.4	-3.9	664.2	-24.5	674.8	-35.2	-	-	712.1	-74.5	674.8	-35.2	-	-	-	-	-	-	-	-	-	No Action		
2612	Tree	649.2	644.5	4.7	664.4	-15.2	675.3	-26.1	-	-	712.3	-43.1	675.3	-26.1	-	-	-	-	-	-	-	-	-	Airspace Study/Removal		
2613	Tree	635.3	644.6	38.8	664.5	19.0	675.4	8.0	-	-	712.5	-25.0	675.4	8.0	-	-	-	-	-	-	-	-	-	Airspace Study/Removal		
2615	Tree	672.3	644.8	27.5	664.7	12.7	675.8	13.7	-	-	712.7	-41.8	675.8	13.7	-	-	-	-	-	-	-	-	-	Airspace Study/Removal		
2616	Tree	632.6	644.9	-12.2	664.8	-32.2	675.8	-43.2	-	-	712.9	-80.2	675.8	-43.2	-	-	-	-	-	-	-	-	-	No Action		
2619	Tree	673.1	645.1	28.1	665.1	8.1	676.1	-3.0	-	-	713.2	-40.1	676.1	-3.0	-	-	-	-	-	-	-	-	-	Airspace Study/Removal		
2621	Tree	637.5	645.2	-7.6	665.2	-26.6	676.2	-36.6	-	-	713.4	-77.6	676.2	-36.6	-	-	-	-	-	-	-	-	-	No Action		
2622	Tree	663.1	645.3	16.0	665.3	-4.0	676.4	-15.1	-	-	713.5	-52.2	676.4	-15.1	-	-	-	-	-	-	-	-	-	Airspace Study/Removal		
2623	Tree	677.2	645.5	31.8	665.5	11.8	676.5	11.6	-	-	713.7	-45.5	676.5	11.6	-	-	-	-	-	-	-	-	-	Airspace Study/Removal		
2624	Bush	640.2	645.5	-5.3	665.6	-25.4	676.7	-36.5	-	-	713.8	-73.7	676.7	-36.5	-	-	-	-	-	-	-	-	-	No Action		
2626	Tree	656.0	645.6	10.4	665.8	0.7	676.9	-20.9	-	-	714.1	-58.1	-	-	-	-	-	-	-	-	-	-	-	Airspace Study/Removal		
2628	Tree	669.0	645.7	23.3	665.9	13.3	677.1	-14.3	-	-	714.3	-61.2	677.1	-14.3	-	-	-	-	-	-	-	-	-	Airspace Study/Removal		
2631	Tree	634.6	645.9	-11.3	666.1	-31.3	677.3	-42.7	-	-	714.5	-80.0	677.3	-42.7	-	-	-	-	-	-	-	-	-	No Action		
2632	Tree	647.7	645.9	3.8	666.1	13.8	677.3	-7.4	-	-	714.6	-29.8	677.3	-7.4	-	-	-	-	-	-	-	-	-	Airspace Study/Removal		
2633	Bush	653.5	646.0	7.5	666.3	20.3	677.5	-14.0	-	-	714.7	-51.3	677.5	-14.0	-	-	-	-	-	-	-	-	-	No Action		
2636	Tree	693.0	646.4	46.6	666.7	26.3	678.0	14.9	-	-	715.3	-22.3	678.0	14.9	-	-	-	-	-	-	-	-</				